

序号	报告编号	发布日期	结论	影像资料
18	GX-B1322/21-1-25030~25040	2025. 2. 12	本次共检验电力电缆11条，11条所检项目合格	 A photograph showing a worker in a blue uniform and red helmet working on a green electrical cabinet. The worker is kneeling on a blue mat, and various tools and equipment are visible on the floor. A timestamp '2025/2/15' is visible in the bottom right corner of the image.
19	GX-B1322/21-1-25041~25044	2025. 2. 12	本次共检验电力电缆4条，4条所检项目合格	 A photograph showing a worker in an orange uniform and red helmet working on a large electrical cabinet in a tunnel. The worker is kneeling on a blue mat, and various tools and equipment are visible on the floor. A timestamp '2025/1/15' is visible in the bottom right corner of the image.

20	GX-B1309/21-1-25001	2025. 2. 12	所检项目合格	 <p>A photograph showing the interior of a tunnel. A worker wearing a red helmet and white clothing is standing on a concrete staircase. To the left, there are several large pipes, some wrapped in green insulation. The tunnel walls are rough and grey. A red timestamp '2025. 01. 08' is visible in the bottom right corner of the image.</p>
21	GX-B1309/21-1-25002	2025. 2. 12	所检项目合格	 <p>A photograph showing the interior of a tunnel. A worker wearing a red helmet and white clothing is standing on a concrete staircase. To the right, there are several large pipes, some wrapped in green insulation. The tunnel walls are rough and grey. A red timestamp '2025. 01. 08' is visible in the bottom right corner of the image.</p>

22	GX-B1500/21-1-25001	2025. 2. 12	综合判定：合格	
23	GX-B1500/21-1-25002	2025. 2. 12	综合判定：合格	

24	GX-B1500/21-1-25003	2025. 2. 12	综合判定：合格	
25	GX-B1500/21-1-25004	2025. 2. 12	综合判定：合格	

26	GX-B1500/21-1-25005	2025. 2. 12	综合判定：合格	 <p>2025.01.08</p>
27	GX-B1500/21-1-25006	2025. 2. 12	综合判定：合格	 <p>2025.01.09</p>


28	GX-B1500/21-1-25007	2025. 2. 12	综合判定：合格	
29	GX-B1500/21-1-25008	2025. 2. 12	综合判定：合格	

30	GX-B1500/21-1-25009	2025. 2. 12	综合判定：合格	 <p>2025 01 09</p>
31	GX-B1308/23-1-25001	2025. 2. 12	综合判定：合格	 <p>2025 01 09</p>

32	GX-B1495/20-1-25059~25068	2025. 2. 13	本次共检高压开关设备10台，10台高压开关设备所检项目合格	 <p>A photograph showing a worker in a blue jacket and helmet kneeling and working on a red high-voltage switchgear cabinet. A date stamp '2025/01/21' is visible in the bottom left corner of the photo.</p>
33	GX-B1495/20-1-25044~25058	2025. 2. 14	本次共检高压开关设备15台，15台高压开关设备所检项目合格	 <p>A photograph showing a worker in a white protective suit and red helmet standing next to a high-voltage switchgear cabinet. The worker is holding a device, possibly a testing instrument. A date stamp '2025/01/21' is visible in the bottom left corner of the photo.</p>

34	GX-B1495/20-1-25030~25043	2025. 2. 13	本次共检高压开关设备14台，14台高压开关设备所检项目合格	
35	GX-B1314/21-1-25004~25007	2025. 2. 14	本次共检验煤矿在用干式电抗器4台，4台煤矿在用干式电抗器所检项目合格	

36	GX-B1321/20-1-25025~25033	2025. 2. 14	本次共检电力电缆9条，9条电力电缆所检项目合格		
37	GX-B1321/20-1-25034~25042	2025. 2. 14	本次共检电力电缆9条，9条电力电缆所检项目合格		

38	GX-B1321/20-1-25043~25053	2025. 2. 14	本次共检电力电缆11条，11条电力电缆所检项目合格	 <p>2025.1.22</p>
39	GX-B1323/21-1-25010~25017	2025. 2. 17	本次共检三相交流电动机8台，8台三相交流电动机所检项目合格	 <p>2025.1.21</p>

40	GX-B1352/21-1-25001~25028	2025. 2. 13	本次共检矿用防爆低压交流真空馈电开关28台, 28台所检项目合格	 <p>2025/1/17</p>
41	GX-B1351/21-1-25001~25002	2025. 2. 17	本次共检矿用防爆型检漏继电器2台, 2台所检项目合格	 <p>2025/1/17</p>

42	GX-B1350/21-1-25001	2025. 2. 17	本次共检接地装置10处, 10处所检项目合格	
43	GX-B1312/20-1-25003~25004	2025. 2. 17	本次共检电力变压器2台, 2台电力变压器所检项目合格	

44	GX-B1312/20-1-25005~25007	2025. 2. 17	本次共检电力变压器3台，3台电力变压器所检项目合格	
45	GX-B1314/21-1-25001~25003	2025. 2. 17	本次共检煤矿在用干式电抗器3台，3台煤矿在用干式电抗器所检项目合格	

46	GX-B1321/20-1-25015~25020	2025. 2. 17	本次共检电力电缆6条，6条电力电缆所检项目合格	 <p>2025.1.17</p>
47	GX-B1321/20-1-25021~25024	2025. 2. 17	本次共检电力电缆4条，4条电力电缆所检项目合格	 <p>2025.1.17</p>

48	GX-B1328/20-1-25008	2025. 2. 17	本次共检绝缘手套6只，6只所检项目合格	
49	GX-B1328/20-1-25009	2025. 2. 17	本次共检绝缘鞋6只，6只所检项目合格	

50	GX-B1328/20-1-25010	2025. 2. 17	本次共检绝缘杆3组，3组所检项目合格	
----	---------------------	-------------	--------------------	-------------------------------------------------------------------------------------