

序号	报告编号	发布日期	结论	影像资料
1	GX-B1374/22-F-250200-250209	2025.4.1	所检项目合格	
2	GX-B1374/22-F-250210-250219	2025.4.1	所检项目合格	

3	GX-B1545/25-F-25061-25062	2025.4.1	本次共检验测定器 2台，2台所检项目合格	 A photograph showing three laboratory technicians in grey uniforms working at a lab bench. They are positioned around a piece of equipment, possibly a detector. The technician in the center has their back to the camera, and the others are facing the equipment. A date stamp '2025.3.21' is visible in the bottom right corner of the image.
4	GX-B1606/23-F-25073-25074	2025.4.1	本次共检验测定器 2台，2台所检项目合格	 A photograph showing three laboratory technicians in grey uniforms working at a lab bench. They are positioned around a piece of equipment, possibly a detector. The technician in the center has their back to the camera, and the others are facing the equipment. A date stamp '2025.3.21' is visible in the bottom right corner of the image.

5	GX-B1373/21-F-25160	2025.4.1	本次共检验传感器 1台，1台所检项目合 格	
6	GX-B1372/22-F-250183-250190	2025.4.1	本次共检验煤矿用低 浓度载体催化式甲烷 传感器8台，8台仪器 所检项目合格	

7	GX-B1601/22-F-250173-250174	2025.4.1	所检项目合格	 <p>2025.3.28</p>
8	GX-B1372/22-F-250170-250180	2025.4.1	所检项目合格	 <p>2025.3.18</p>

9	GX-B1465/22-F-25039	2025.4.1	所检项目合格	 <p>2025.3.19</p>
10	GX-B1373/21-F-25151-25152	2025.4.1	所检项目合格	 <p>2025.3.19</p>

11	GX-B1466/22-F-25028-25030	2025.4.1	所检项目合格	
12	GX-B1374/22-F-250285	2025.4.1	所检项目合格	

13	GX-B1542/21-F-25065-25073	2025.4.1	所检项目合格	 <p>2025.3.22</p>
14	GX-B1529/20-F-25066-25067	2025.4.1	所检项目合格	 <p>2025.3.23</p>

15	GX-B1528/20-F-25049-25055	2025.4.1	所检项目合格	
16	GX-B1529/20-F-25068-25074	2025.4.1	所检项目合格	

17	GX-B1543/25-F-25063-25069	2025.4.1	所检项目合格	
18	GX-B1374/22-F-250273-250274	2025.4.1	所检项目合格	

19	GX-B1410/22-F-25195-25208	2025.4.1	所检项目合格	 A photograph showing two male technicians in grey lab coats working in a laboratory. They are positioned in front of a blue cabinet with various pieces of equipment on top. The technician on the right is holding a small object, possibly a sample or a tool. A yellow timestamp '2025.3.21' is visible in the bottom right corner of the image.
20	GX-B1592/21-F-25032-25033	2025.4.1	所检项目合格	 A photograph showing two female technicians in grey lab coats working in a laboratory. They are positioned in front of a blue cabinet with various pieces of equipment on top. The technician on the right is holding a small object, possibly a sample or a tool. A yellow timestamp '2025.4.1' is visible in the bottom right corner of the image. The lab coat of the technician in the foreground has the logo '中检公信' (China Inspection and Certification) on the back.

21	GX-B1595/22-F-25034~25047	2025.4.2	所检项目合格	
22	GX-B1373/21-F-25129~25137	2025.4.2	所检项目合格	

23	GX-B1601/22-F-250109~250115	2025.4.2	所检项目合格	 <p>2025.3.13</p>
24	GX-B1603/22-F-250046	2025.4.2	所检项目合格	 <p>2025.3.13</p>

25	GX-B1465/22-F-25017~25029	2025.4.2	所检项目合格	 <p>2025.3.14</p>
26	GX-B1372/22-F-250144~250147	2025.4.2	所检项目合格	 <p>2025.3.10</p>

27	GX-B1466/22-F-25025	2025.4.2	所检项目合格	
28	GX-B1602/22-F-25019	2025.4.2	所检项目合格。	

29	GX-B1601/22-F-25166	2025.4.2	所检项目合格	
30	GX-B1602/22-F-25015~25018	2025.4.2	所检项目合格	

31	GX-B1603/22-F-250059~250060	2025.4.2	所检项目合格	 <p>2025/3/28</p>
32	GX-B1410/22-F-25209-25212	2025.4.2	所检项目合格	 <p>2025.3.24</p>



33	GX-B1592/21-F-25036-25038	2025.4.2	所检项目合格	 <p>2025.3.25</p>
34	GX-B1606/23-F-25075-25081	2025.4.2	所检项目合格	 <p>2025.3.26</p>

35	GX-B1605/23-F-25075-25081	2025.4.2	所检项目合格	 <p>2025.3.26</p>
36	GX-B1601/21-F-250158-250161	2025.4.2	所检项目合格	 <p>2025.3.24</p>

37	GX-B1411/22-F-25014	2025.4.2	所检项目合格	
38	GX-B1475/22-F-25162-25168	2025.4.2	所检项目合格	

39	GX-B1540/20-F-250538-250562	2025.4.2	所检项目合格	
40	GX-B1540/20-F-250563-250587	2025.4.2	所检项目合格	

41	GX-B1540/20-F-250588-250591	2025.4.2	所检项目合格	 <p>2025.3.23</p>
42	GX-B1540/20-F-250592-250598	2025.4.2	所检项目合格	 <p>2025.3.23</p>

43	GX-B1372/22-F-250242	2025.4.2	所检项目合格	 <p>2025.3.24</p>
44	GX-B1373/21-F-25164	2025.4.2	所检项目合格	 <p>2025.3.24</p>

45	GX-B1593/21-F-25061~25066	2025.4.3	本次共检验烟雾传感器6台，6台所检项目合格	
46	GX-B1593/21-F-25067-25069	2025.4.3	本次共检验烟雾传感器3台，3台所检项目合格。	

47	GX-B1603/22-F-250064~250065	2025.4.3	本次共检测粉尘浓度传感器2台，2台所检项目合格。	
48	GX-B1603/22-F-250061~250063	2025.4.3	本次共检测粉尘浓度传感器3台，3台所检项目合格。	

49	GX-B1601/22-F-250175	2025.4.3	所检项目合格	
50	GX-B1529/20-F-25077	2025.4.2	所检项目合格	

51	GX-B1568/22-F-25080~25081	2025.4.2	所检项目合格	 <p>2025.3.24</p>
52	GX-B1602/22-F-25011~25012	2025.4.2	所检项目合格	 <p>2025.3.26</p>

53	GX-B1568/22-F-25070~25079	2025.4.2	所检项目合格	
54	GX-B1593/21-F-25056~25057	2025.4.3	所检项目合格	

55	GX-B1410/22-F-25213~25215	2025.4.3	所检项目合格	 A photograph showing two technicians in a laboratory or testing facility. They are wearing grey jackets with a logo that says '中检公信' (China Inspection and Certification). They are standing next to a piece of electronic equipment on a blue counter. The date '2025/3/27' is visible in the bottom right corner of the photo.
56	GX-B1601/22-F-250167~250172	2025.4.3	所检项目合格	 A photograph showing a technician in a grey jacket sitting at a workstation in a laboratory. The technician is looking at a computer monitor displaying a software interface. In the background, there are other pieces of equipment and another person. The date '2025/3/27' is visible in the bottom right corner of the photo.


57	GX-B1601/22-F-250180	2025.4.2	所检项目合格	 <p>2025.3.29</p>
58	GX-B1593/21-F-25070-25075	2025.4.2	所检项目合格	 <p>2025.3.30</p>

59	GX-B1373/21-F-25161-25163	2025.4.2	所检项目合格	
60	GX-B1372/22-F-250235-250241	2025.4.2	所检项目合格	

61	GX-B1374/22-F-250275-250283	2025.4.2	所检项目合格	
62	GX-B1529/20-F-25075-25076	2025.4.2	所检项目合格	

63	GX-B1542/21-F-25074-25085	2025.4.2	所检项目合格	
64	GX-B1542/21-F--25086-25095	2025.4.3	所检项目合格	

65	GX-B1542/21-B-25031~25037	2025.4.7	所检项目合格	 <p>2025.2.10</p>
66	GX-B1542/21-F-25096~25107	2025.4.7	所检项目合格	 <p>2025.3.26</p>

67	GX-B1568/22-F-25082~25087	2025.4.7	所检项目合格	
----	---------------------------	----------	--------	---