


序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-7-25232	2025.12.1	符合标准要求。	 A photograph showing a worker in a bright orange protective suit and helmet standing next to a large, red industrial machine, possibly a conveyor belt or processing unit. The worker is facing the machine. The date '2025/11/19' is visible in the bottom right corner of the image.
2	GX-B1310/21-7-25233	2025.12.1	符合标准要求。	 A photograph of a worker in an orange suit and helmet working inside a dark, confined space, likely a tunnel or industrial duct. The worker is illuminated by a headlamp and is reaching up towards a circular opening. The date '2025/11/19' is visible in the bottom right corner of the image.

3	GX-B1310/21-7-25234	2025.12.1	符合标准要求。		
4	GX-B1310/21-7-25235	2025.12.1	符合标准要求。		



5	GX-B1428/21-7-25235	2025.12.1	无缺陷迹痕显示		
6	GX-B1310/21-7-25236	2025.12.1	符合标准要求。		

7	GX-B1428/21-7-25236	2025.12.1	无缺陷迹痕显示			
8	GX-B1310/21-7-25219	2025/12/2	符合标准要求			

9	GX-B1310/21-7-25220	2025/12/2	符合标准要求		
10	GX-B1310/21-7-25221	2025/12/2	符合标准要求		

11	GX-B1310/21-7-25222	2025/12/2	符合标准要求		
12	GX-B1310/21-7-25223	2025/12/2	符合标准要求		

13	GX-B1302/25-7-25012	2025/12/4	所检项目合格。	
14	GX-B1515/22-7-25007	2025/12/8	所检项目合格。	

15	GX-B1515/22-7-25008	2025/12/8	所检项目合格。	 2025/10/15
16	GX-B1321/20-7-25815~25816	2025/12/5	本次共检电力电缆2条，2条电力电缆所检项目合格。	 2025/11/23

17	GX-B1328/25-7-25130	2025/12/8	本次共检绝缘手套12只，12只绝缘手套合格。	
18	GX-B1328/25-7-25131	2025/12/8	绝缘靴12只，12只绝缘	

19	GX-B1308/23-7-25021	2025.12.8	综合判定：合格。		 2025.11.6	
20	GX-B1310/21-7-25237	2025/12/8	符合标准要求		 2025/11/22	

21	GX-B1428/21-7-25237	2025/12/8	无缺陷迹痕显示	
22	GX-B1385/21-7-25026	2025. 12. 8	所检项目合格。	

23	GX-B1312/20-7-25661~25662	2025/12/8	本次共检电力变压器2台，2台电力变压器所检项目合格。		
24	GX-B1312/20-7-25664~25666	2025/12/8	本次共检电力变压器3台，3台电力变压器所检项目合格。		

25	GX-B1495/25-7-252310~252316	2025/12/8	本次共检高压防爆开关7台，7台高压防爆开关所检项目合格。	 2025/11/23	
26	GX-B1495/25-7-252303~252309	2025/12/8	本次共检高压开关柜7台，7台高压开关柜所检项目合格。	 2025/11/23	