

序号	报告编号	发布日期	结论	影像资料
27	GX-B1310/21-7-25238	2025/12/8	符合标准要求	
28	GX-B1310/21-7-25239	2025/12/8	符合标准要求	

29	GX-B1428/21-7-25238	2025/12/8	无缺陷迹痕显示	
30	GX-B1428/21-7-25239	2025/12/8	无缺陷迹痕显示	


31	GX-B1302/25-7-25013	2025/12/9	综合判定：合格。		2025/11/22
32	GX-B1310/21-7-25242	2025.12.10	符合标准要求。		2025.11.20

33	GX-B1310/21-7-25243	2025.12.10	符合标准要求。		 2025.11.20	
34	GX-B1310/21-7-25244	2025.12.10	符合标准要求。		 2025.11.20	

35	GX-B1310/21-7-25240	2025.12.10	符合标准要求。		 2025.11.18	
36	GX-B1310/21-7-25241	2025.12.10	符合标准要求。		 2025.11.18	

37	GX-B1385/21-7-25029	2025/12/10	所检项目合格。		 2025/11/22	
38	GX-B1385/21-7-25030	2025/12/10	所检项目合格。		 2025/11/23	

39	GX-B1515/22-7-25009	2025/12/11	所检项目合格。	 2025/10/21	
40	GX-B1321/20-7-25817~25820	2025/12/11	本次共检电力电缆4条，4条电力电缆所检项目合格。	 2025/12/1	

41	GX-B1310/21-7-25246	2025/12/12	符合标准要求。		2025/12/8
----	---------------------	------------	---------	---	-----------