


序号	报告编号	发布日期	结论	影像资料
21	GX-B1378/22-B-25407~B-25410	2025. 12. 24	所检项目合格	
22	GX-B1378/22-B-25403~B-25406	2025. 12. 24	所检项目合格	

23	GX-B1489/21-B-25152	2025. 12. 24	所检项目合格	 <p>2025.12.19</p>
24	GX-B1489/21-B-25153	2025. 12. 24	所检项目合格	 <p>2025.12.19</p>

25	GX-B1377/22-B-25290	2025. 12. 24	所检项目合格	
26	GX-B1377/22-B-25291~25295	2025. 12. 24	所检项目合格	

27	GX-B1377/22-B-25296~25299	2025. 12. 24	所检项目合格	
28	GX-B1489/21-B-25157~B-25158	2025. 12. 29	所检项目合格	

29	GX-B1489/21-B-25159	2025. 12. 29	所检项目合格	 <p>2025.12.23</p>
30	GX-B1489/21-B-25154	2025. 12. 29	所检项目合格	 <p>2025.12.22</p>

31	GX-B1489/21-B-25155~B-25156	2025. 12. 29	所检项目合格	
32	GX-B1492/21-B-25074	2025. 12. 29	所检项目合格	

33	GX-B1492/21-B-25075	2025. 12. 29	所检项目合格	 A photograph showing two men in a room with yellow curtains. One man in a black jacket is standing and looking at a white machine on a table. The other man in a grey jacket is sitting at the table, also looking at the machine. The machine has a circular logo on its front. The date '2025.12.22' is visible in the bottom right corner of the photo.
34	GX-B1460/22-B-25007	2025. 12. 29	所检项目合格	 A photograph showing two men in a room with yellow curtains. One man in a black jacket is standing and looking at a white machine on a table. The other man in a grey jacket is sitting at the table, also looking at the machine. The machine has several hoses connected to it. A yellow warning sign is visible on the wall in the background. The date '2025.12.22' is visible in the bottom right corner of the photo.